

# Pt 1000 temperature probe

## Pt 1000 temperature sensor



Model number	<b>S-PT1000</b>
Probe	Φ 6 mm × 50 mm
Cable	2 m
<b>Used for:</b>	
12 temperature sensors inputs	<a href="#">AIR-12</a>

From:  
<http://wiki.hiq-universe.com/> -

Permanent link:  
[http://wiki.hiq-universe.com/doku.php?id=en:hiq\\_hw:s-pt1000&rev=1565779794](http://wiki.hiq-universe.com/doku.php?id=en:hiq_hw:s-pt1000&rev=1565779794)

Last update: **2019/08/14 10:49**

